

Fig. 1
(PRIOR ART)




Fig. 2
(PRIOR ART)

This exploded perspective view illustrates the assembly 10. At the top, a bolt 18 is shown with a dashed line indicating its path through a nut 19 and a flange 16. Below this, a central component 12 is shown, which includes a top flange 14 with a central hole 21, a middle section 24 with a central hole 31, and a bottom flange 26 with a central hole 33. A rectangular block 35 is positioned between the top and middle sections. A dashed line 34 indicates the assembly path. To the right, a bracket 36 is shown with two curved arms 40 and 44. Below the bracket, a nut 20 is shown with a washer 38. At the bottom, a nut 30 is shown with a washer 42. A dashed line 35 indicates the assembly path for the bracket. At the bottom, three screws 28 are shown with dashed lines indicating their path through the bottom flange 26.

Fig. 3

10082678.022502




Fig. 5A




Fig. 5B






Fig. 6A






Fig. 7A




Fig. 7B

10082678-0225022










Fig. 8











Fig. 14.





545




FIG. 20

